










110330000QN/04-2021

ISTRUZIONI - INSTRUCTIONS - INSTRUCTIONS - INSTRUCCIONES - ANLEITUNG










Blocco a 90°
90° block
Bloqueo a 90°
Blocage à 90°
90°-Sperr






NON SONO IN DOTAZIONE
NOT IN EQUIPMENT
NO ESTAN EN DOTACION
MATERIEL PAS FOURNI
NICHT IN DER
AUSRÜSTUNG

TSP 4,2X25





Blocco a 90°
90° block
Bloqueo a 90°
Blocage à 90°
90°-Sperre



NON SONO IN DOTAZIONE
NOT IN EQUIPMENT
NO ESTAN EN DOTACION
MATÉRIEL PAS FOURNI
NICHT IN DER
AUSRÜSTUNG

TSP 4,2X25

